



1. Tools and Components needed






2. Remove the Kevlar coating






3. Prepare Maxiglide for connectors






3. Attach the inner connector



































Turn the threaded ring and front cap clockwise. Do not turn the allen key.



4. Mount the connector cap







4. Mount the connector cap



